

2023.04.04: V1.2.5

Optimize the problem of wind speed and direction remaining unchanged after rain.

2023.01.20: V1.2.4

Optimize low/no wind speed detection algorithm.

2022.05.17: V1.2.2

Optimize wind speed measurement algorithm.

Optimize gust speed data handling algorithm to have more stable output.

adjust light sensor gain.

bootloader changed so that USB port can be used for possible factor write control.

2022.03.02: V1.2.1

1. FSK chip bus driver optimized to achieve better performance.
2. An correction to wind speed at SE or NW direction for better wind speed accuracy
3. Sensor ID generation Alogorithm improved.

2021. 12.23: v1.2.0 There is a possible I2C data bus conflict can happen due to working window time overlaping related. we optimized the bus driver. Those customer that has temperature/humidity data problem should be encouraged to upgrade. This fix is working for SHT40 sensors used. So those with STH30 sensor is not necessary.

2021.09.09: v1. 1.8 During rain time, sometimes abnormal wind speed was detected due to water accumulation influence to the hardware.

We improved the signal qualification process and have the data filtered more precisely for those untable signal influence.

The new firmware has been tested in Australia and New Zealand during raining time and heavy wind condition, and after about two weeks testing, there is none error wind data detected. So we believe this version solved this problem in a very good way.